

A 700/900mW/Channel CMOS Dual Analog
Front-End IC for VDSL with Integrated
11.5/14.5dBm Line Drivers

**M. Moyal, M. Groepl, H. Werker,
G. Mitteregger, J. Schambacher**


Xignal Technologies AG, Munich, Germany

Outline

Dual Channel VDSL AFE


- Overview
- Architecture
- Circuit Implementations
- Measured Performances
- Summary

Overview




- VDSL-AFE for CO and CPE
- $0.25/0.5\mu\text{m}$ 5M 1P CMOS, MIM-Capacitors, Poly-Resistors
- Emphasis on power saving
- Almost no external components


Overview continued




Architecture Per Channel



Transmitter Implementation: DAC




Transmitter: Post Filter




- 4th order Butterworth, f_{-3dB} 18MHz, calibrated at power up
- 14dB Power back-off in 1dB steps


OPAMP CONCEPT




OPAMP CORE




Line Driver




Hybrid / VGA




Hybrid / VGA (next revision)




ADC




ADC GM-STAGE



ADC COMPARATOR




LC-PLL CIRCUIT



Measurements


- Transmit Path and Line Driver
- Receive Path
- PLL

Transmit Path- Measurement 1





14.5 dBm signals for
power measurements
and functional tests

Transmit Path- Measurement 2



Line Driver IM3-Measurement




10MHz + 11MHz full scale

Input signal subtracted

IM3: below -83dBc


Receive Path- Measurement




2.1MHz (-1dBfs)
14 dB VGA gain

BW = 12MHz
SNR = 72dB
THD = 71dB

240MHz-PLL Measurement



Die Photo



Summary

- Dual Channel VDSL AFE
- Integrated Line Driver
- 900mW/channel power consumption at 14.5dBm line power
- 23mm²/channel (31mm² with test structures)
- 12b TX-performance at 12MHz signal bandwidth
- 12b RX-performance at 12MHz signal bandwidth

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.